

Condition: 1 = Good, 2 = Satisfactory, 3 = Poor

Path No	Condition	PARISH NAME	Status (Fp, Bw, Rb, Boat)	Surveyor	Survey Date
3	2	Thorner Parish Council	FP	Victoria Goodall	14/09/2013

Issue Type Key: V = Vegetation, M = Maintenance, DM = Definitive Map, E = Enforcement, F = Fly Tipping, O = Other

Issue No	Issue type	Issue /Problem (V ~M~DM~E~F~O)	Comments	Action Needed	Action Taken
1	M	Path Breaking Up	LCC are responsible as break up is due to water running of the A58 - they have looked at it previously but needs re-doing.	Path Repair	
3					
4					
5					

