


**Condition: 1 = Good, 2 = Satisfactory, 3 = Poor**

Path No	Condition	PARISH NAME	Status (Fp, Bw, Rb, Boat)	Surveyor	Survey Date
6	1	<b>Thorner Parish Council</b>	FP	Victoria Goodall	14/09/2013

**Issue Type Key: V = Vegetation, M = Maintenance, DM = Definitive Map, E = Enforcement, F = Fly Tipping, O = Other**

Issue No	Issue type	Issue /Problem (V ~M~DM~E~F~O)	Comments	Action Needed	Action Taken
1	M	Loose Stile		Stile Repair	
2	V	Overgrown Hedges along path	Picture 01	Hedge needs cutting	
4					
5					



Title



= Photograph

Footpath no 06



= Issue no



Path 06 - photo record

1

